

NOTES:

- 1) IF EXISTING PENETRATION IS CONTAMINATED, COVER WITH ALUMINUM TAPE AND USE SIKALASTOMER-65 UNDER HOSE CLAMP. ALTERNATIVE IS TO ELIMINATE ALUMINUM TAPE AND USE SARNAFIL G 459 FLASHING MEMBRANE AND SIKALASTOMER-65 UNDER HOSE CLAMP.
- 2) SEALANT IS A MAINTENANCE ITEM AND IS NOT COVERED UNDER THE SARNAFIL WARRANTY.

ONEDEK PIPE PENETRATION FLASHING

