

- 1) SIKA SARNAFIL IS NOT RESPONSIBLE FOR DAMAGE TO THE SIKA SARNAFIL ROOF AS A RESULT FROM LIGHTNING AND OR THE LIGHTNING ROD ASSEMBLY.
- 2) VAPOR RETARDER SHALL BE SEALED AT EDGES.

LIGHTNING ROD

