

## NOTES:

- 1) SUBSEQUENT LAYERS AND OVERBURDEN NOT SHOWN FOR CLARITY.
- 2) THREE WAY OVERLAP PATCHES NOT SHOWN FOR CLARITY.
- 3) SEALANT IS A MAINTENANCE ITEM NOT COVERED UNDER SIKA SARNAFIL WARRANTY.
- 4) THE BACK OF THE G459 FLASHING AND GRID STRIP MEMBRANE MUST BE PRIMED WITH SIKAFLEX PRIMER 449.

## THRESHOLD (ISOMETRIC)

