


# SIKA® TILT WALL SOLUTIONS

## TYPICAL TILT WALL REPAIRS



### A. Sacking

- SikaQuick® Smooth Finish

### B. Joint Sealing + Glazing

- Sikaflex® NP 2
- Sikasil® WS-305
- Sikaflex® HY 100
- Sikaflex®-2c NS EZ Mix +

### C. Floor Joint

- Sika® Loadflex-524 EZ
- Sikadur®-58 CJR

### D. Expansion Joints (interior)

- Sikaflex® 1c SL
- Sikaflex® 2c SL
- Sikaflex®-SL 1
- Sikaflex®-SL 2

### E. Coatings

- Sika Thorocoat®-100 TW
- Sika Thorocoat®-200 LR
- Sika Thorocoat®-400
- Sika Thorocoat®-250
- Sika Thorocoat®-350

### F. Curing & Sealing

- Sikagard®-200 Enviroseal
- Sikagard®-400 Enviroseal
- Sikagard® 1315 KNS
- Sikagard®-440 Clear
- Sikagard®-300 HD WB

### G. Patching

- SikaQuick® VOH (Vertical)
- SikaQuick®-1000 (Horizontal)
- SikaQuick®-2500 (Horizontal)
- SikaQuick® EZ Patch (Horizontal)
- SikaEmaco®-1060 (Horizontal)
- SikaEmaco®-1061 (Horizontal)
- SikaEmaco® 425 Gel Patch (Vertical)

### H. Grouting

- SikaGrout®-212
- SikaGrout®-328

### I. Floor Treatments

- Sikafloor® MetalTop-200
- Sikagard®-300 HD WB

SCAN HERE:





# FOR MORE SIKA® INFORMATION:

Visit: [www.usa.sika.com](http://www.usa.sika.com) Phone: 800-933-SIKA

**Sika Corporation**

201 Polito Avenue,  
Lyndhurst, NJ 07071  
Phone: 201-933-8800  
Fax: 201-933-6225

**BUILDING TRUST**

