

Revision Date 06/05/2024

Print Date 06/05/2024

SECTION 1. IDENTIFICATION

Product name	:	Sikagard [®] -75 EpoCem [®] CA Part C
Company name	:	Sika Corporation
		201 Polito Avenue Lyndhurst, NJ 07071 USA www.sikausa.com
Telephone	:	(201) 933-8800
Telefax	:	(201) 804-1076
E-mail address	:	ehs@sika-corp.com
Emergency telephone	:	CHEMTREC: 800-424-9300 INTERNATIONAL: +1-703-527-3887
Recommended use of the chemical and restrictions on use	:	For further information, refer to product data sheet.

SECTION 2. HAZARDS IDENTIFICATION

GHS classification in accordance with the OSHA Hazard Communication Standard (29 CFR 1910.1200)

Skin corrosion	:	Category 1C
Serious eye damage	:	Category 1
Skin sensitization	:	Category 1
Carcinogenicity (Inhalation)	:	Category 1A
Specific target organ toxicity - single exposure	:	Category 3 (Respiratory system)
Specific target organ toxicity - repeated exposure	:	Category 1 (Lungs)
GHS label elements Hazard pictograms	:	
Signal Word	:	Danger
		1 / 13

Revision Date 06/05/2024



Print Date 06/05/2024

Hazard Statements :	 H314 Causes severe skin burns and eye damage. H317 May cause an allergic skin reaction. H335 May cause respiratory irritation. H350 May cause cancer by inhalation. H372 Causes damage to organs (Lungs) through prolonged or repeated exposure.
Precautionary Statements :	Prevention:
	 P201 Obtain special instructions before use. P202 Do not handle until all safety precautions have been read and understood. P260 Do not breathe dust. P264 Wash skin thoroughly after handling. P270 Do not eat, drink or smoke when using this product. P271 Use only outdoors or in a well-ventilated area. P272 Contaminated work clothing must not be allowed out of the workplace. P280 Wear protective gloves/ protective clothing/ eye protection/ face protection.
	Response:
	 P301 + P330 + P331 IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. P303 + P361 + P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water/ shower. P304 + P340 + P310 IF INHALED: Remove person to fresh air and keep comfortable for breathing. Immediately call a POISON CENTER/ doctor. P305 + P351 + P338 + P310 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER/ doctor. P308 + P313 IF exposed or concerned: Get medical advice/ attention. P333 + P313 If skin irritation or rash occurs: Get medical advice/ attention. P362 + P364 Take off contaminated clothing and wash it before reuse.
	Storage: P403 + P233 Store in a well-ventilated place. Keep container tightly closed. P405 Store locked up.
	Disposal: P501 Dispose of contents/ container to an approved waste disposal plant.

Additional Labeling

There are no ingredients with unknown acute toxicity used in a mixture at a concentration >= 1%.



Revision Date 06/05/2024

Print Date 06/05/2024

Other hazards

None known.

SECTION 3. COMPOSITION/INFORMATION ON INGREDIENTS

Mixtures

Components

Chemical name	CAS-No.	Classification	Concentra- tion (% w/w)
Quartz (SiO2) >5µm	14808-60-7	Carc. 1A; H350 STOT RE 1; H372 STOT SE 3; H335	>= 50 - < 70
Portland Cement	65997-15-1	Skin Corr. 1C; H314 Eye Dam. 1; H318 Skin Sens. 1; H317 STOT SE 3; H335	>= 30 - < 50
fumes, silica	69012-64-2		>= 1 - < 5

Actual concentration is withheld as a trade secret

SECTION 4. FIRST AID MEASURES

General advice :	Move out of dangerous area. Consult a physician. Show this material safety data sheet to the doctor in attend- ance.
If inhaled :	Move to fresh air. Consult a physician after significant exposure.
In case of skin contact :	Take off contaminated clothing and shoes immediately. Wash off with soap and plenty of water. Immediate medical treatment is necessary as untreated wounds from corrosion of the skin heal slowly and with difficul- ty.
In case of eye contact :	Small amounts splashed into eyes can cause irreversible tis- sue damage and blindness. In the case of contact with eyes, rinse immediately with plenty of water and seek medical advice. Continue rinsing eyes during transport to hospital. Remove contact lenses. Keep eye wide open while rinsing.
If swallowed :	Clean mouth with water and drink afterwards plenty of water. Do not induce vomiting without medical advice. Do not give milk or alcoholic beverages. Never give anything by mouth to an unconscious person. Take victim immediately to hospital.

Revision Date 06/05/2024

Jika®

Print Date 06/05/2024

Most important symptoms and effects, both acute and delayed	 Prolonged exposure can cause silicosis. Cough Respiratory disorder Allergic reactions Dermatitis Health injuries may be delayed. corrosive effects irritant effects sensitizing effects May cause an allergic skin reaction. Causes serious eye damage. May cause respiratory irritation. May cause respiratory irritation. Causes damage to organs through prolonged or repeated exposure. Causes severe burns.
Notes to physician	: Treat symptomatically.

SECTION 5. FIRE-FIGHTING MEASURES

Suitable extinguishing media	:	Use extinguishing measures that are appropriate to local cir- cumstances and the surrounding environment.
Further information	:	Collect contaminated fire extinguishing water separately. This must not be discharged into drains. Fire residues and contaminated fire extinguishing water must be disposed of in accordance with local regulations.
Special protective equipment for fire-fighters	:	In the event of fire, wear self-contained breathing apparatus.

SECTION 6. ACCIDENTAL RELEASE MEASURES

Personal precautions, protec- :	Use personal protective equipment.
tive equipment and emer-	Avoid breathing dust.
gency procedures	Deny access to unprotected persons.
Environmental precautions :	Do not flush into surface water or sanitary sewer system. If the product contaminates rivers and lakes or drains inform respective authorities. Local authorities should be advised if significant spillages cannot be contained.
Methods and materials for :	Pick up and arrange disposal without creating dust.
containment and cleaning up	Keep in suitable, closed containers for disposal.

SECTION 7. HANDLING AND STORAGE

Revision Date 06/05/2024



Print Date 06/05/2024

Advice on protection against fire and explosion	:	Avoid dust formation. Provide appropriate exhaust ventilation at places where dust is formed.
Advice on safe handling	:	 Avoid formation of respirable particles. Avoid exceeding the given occupational exposure limits (see section 8). Do not get in eyes, on skin, or on clothing. For personal protection see section 8. Persons with a history of skin sensitization problems or asthma, allergies, chronic or recurrent respiratory disease should not be employed in any process in which this mixture is being used. Smoking, eating and drinking should be prohibited in the application area. Follow standard hygiene measures when handling chemical products.
Conditions for safe storage	:	Store in original container. Keep in a well-ventilated place. Observe label precautions. Store in accordance with local regulations.
Materials to avoid	:	Explosives Oxidizing agents Poisonous gases Dangerous when wet Flammable solids Organic peroxides Poisonous liquids Spontaneously Combustible Substances
Further information on stor- age stability	:	Keep in a dry place. No decomposition if stored and applied as directed.

SECTION 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Ingredients with workplace control parameters

Components	CAS-No.	Value type (Form of exposure)	Control parame- ters / Permissible concentration	Basis
Quartz (SiO2) >5µm	14808-60-7	TWA (Res- pirable par- ticulate mat- ter)	0.025 mg/m3	ACGIH
		TWA (Res- pirable dust)	0.05 mg/m3	OSHA Z-1
		TWA (respir- able)	10 mg/m3 / %SiO2+2	OSHA Z-3
		TWA (respir- able)	250 mppcf / %SiO2+5	OSHA Z-3



Revision Date 06/05/2024

Print Date 06/05/2024

TWA (Res- pirable par- ticulate mat- ter)0.025 mg/m3 (Silica)ACGIHPEL (respir- able)0.05 mg/m3OSHA CARC able)TWA (respir- able dust fraction)0.05 mg/m3OSHA CARC other other trable dust ter)0.025 mg/m3OSHA P0TWA (Res- pirable par- ticulate mat- ter)0.025 mg/m3OSHA P0OSHA P0Portland Cement65997-15-1TWA (Res- pirable par- ticulate mat- ter)0.025 mg/m3ACGIHPortland Cement65997-15-1TWA (Res- pirable par- ticulate mat- ter)1 mg/m3OSHA Z-1Portland Cement65997-15-1TWA (Res- pirable par- ticulate mat- ter)1 mg/m3OSHA Z-1TWA (respir- able fraction)1 mg/m3OSHA Z-1OSHA Z-1TWA (respir- able fraction)5 mg/m3OSHA Z-1TWA (respir- able fraction)5 mg/m3OSHA P0TWA (Respirable frac- tion)10 mg/m3OSHA P0TWA (Du			TWA (respir- able dust fraction)	0.1 mg/m3	OSHA P0
PEL (respir- able) 0.05 mg/m3 of mg/m3 OSHA CARC TWA (respir- able dust fraction) 0.1 mg/m3 OSHA P0 TWA (Res- pirable par- ticulate mat- ter) 0.025 mg/m3 ACGIH Portland Cement 65997-15-1 TWA (Res- pirable par- ticulate mat- ter) 0.025 mg/m3 ACGIH Portland Cement 65997-15-1 TWA (Res- pirable par- ticulate mat- ter) 1 mg/m3 ACGIH Portland Cement 65997-15-1 TWA (total dust) 15 mg/m3 OSHA Z-1 TWA (total dust) 15 mg/m3 OSHA Z-1 OSHA Z-1 TWA (total dust) 10 mg/m3 OSHA P0 OSHA P0 TWA (respir- able fraction) 5 mg/m3 OSHA P0 OSHA P0 TWA (Respir- able fraction) 10 mg/m3 OSHA P0 OSHA P0 TWA (Respir- able fraction) 50 Million parti- cles per cubic foot (Silica) OSHA P0 TWA (Res- pirable fraction) 10 mg/m3 OSHA P0 TWA (Dust) 80 mg/m3 OSHA P0 TWA (Dust) 20 Million parti- cles per cubic foot (Silica) OSHA Z-3 TWA (Dust) 80 mg/m3 / %SiO2 OSHA			TWA (Res- pirable par- ticulate mat-		ACGIH
TWA (respirable dust fraction)0.1 mg/m3 mg/m3OSHA P0TWA (Respirable particulate matter)TWA (Respirable particulate matter)0.025 mg/m3 mg/m3ACGIHPortland Cement65997-15-1TWA (Respirable particulate matter)(Silica)ACGIHPortland Cement65997-15-1TWA (Respirable particulate matter)11 mg/m3ACGIHPortland Cement65997-15-1TWA (Respirable particulate matter)15 mg/m3OSHA Z-1Image: SilicaTWA (total dust)15 mg/m3OSHA Z-1Image: SilicaTWA (total dust)5 mg/m3OSHA Z-1Image: SilicaTWA (respirable particulate matter)10 mg/m3OSHA Z-1Image: SilicaTWA (respirable particulate matter)5 mg/m3OSHA Z-1Image: SilicaTWA (respirable particulate matter)0SHA P00SHA P0Image: SilicaTWA (respirable particulate matter)0SHA P00SHA P0Image: SilicaTWA (respirable fraction)50 Million particulate foot0SHA P0Image: Silica69012-64-2TWA (Dust)20 Million particulate foot0SHA P0Image: SilicaSilicaTWA (Dust)20 Million particulate foot0SHA Z-3Image: SilicaTWA (Dust)80 mg/m3 / %SIO20SHA Z-3Image: SilicaTWA (Dust)<			PEL (respir-	0.05 mg/m3	OSHA CARC
TWA (Respirable particulate matter) 0.025 mg/m3 ACGIH Portland Cement 65997-15-1 TWA (Respirable particulate matter) 0.025 mg/m3 ACGIH Portland Cement 65997-15-1 TWA (Respirable particulate matter) 1 mg/m3 ACGIH Image: Straight Comparison of the particulate matter) 1 mg/m3 ACGIH ACGIH Image: Straight Comparison of the particulate matter) 1 mg/m3 ACGIH ACGIH Image: Straight Comparison of the particulate matter) 1 mg/m3 OSHA Z-1 ACGIH Image: Straight Comparison of the particulate matter) 15 mg/m3 OSHA Z-1 ACGIH Image: Straight Comparison of the particulate matter) 10 mg/m3 OSHA Z-1 ACGIH Image: Straight Comparison of the particulate matter) 5 mg/m3 OSHA P0 ACGIH Image: Straight Comparison of the particulate matter) 10 mg/m3 OSHA P0 ACGIH Image: Straight Comparison of the particulate matter) 5 mg/m3 OSHA P0 ACGIH Image: Straight Comparison of the particulate matter) 10 mg/m3 OSHA P0 ACGIH Image: Straight Comparison of the particulate matter) 10 mg/m3 OSHA P0 ACGIH <			TWA (respir- able dust	0.1 mg/m3	OSHA P0
pirable par- ticulate mat- ter)(Silica)Portland Cement65997-15-1TWA (Res- pirable par- ticulate mat- ter)1 mg/m3ACGIHPortland Cement65997-15-1TWA (Res- pirable par- ticulate mat- ter)1 mg/m3OSHA Z-1Image: SilicaImage: SilicaTWA (total dust)15 mg/m3OSHA Z-1Image: SilicaImage: SilicaImage: SilicaOSHA Z-1Image: SilicaImage: SilicaImage: SilicaOSHA POImage: SilicaImage: Sil			TWA (Res- pirable par- ticulate mat-	0.025 mg/m3	ACGIH
pirable par- ticulate mat- ter)pirable par- ticulate mat- ter)NTWA (total dust)TWA (total dust)15 mg/m3OSHA Z-1TWA (respir- able fraction)5 mg/m3OSHA Z-1TWA (Total dust)10 mg/m3OSHA POTWA (respir- able dust fraction)5 mg/m3OSHA POTWA (respir- able dust fraction)5 mg/m3OSHA POTWA (respir- able dust fraction)5 mg/m3OSHA POTWA (Dust)50 Million parti- cles per cubic footOSHA Z-3TWA (Total)10 mg/m3OSHA POTWA (Total)10 mg/m3OSHA POfumes, silica69012-64-2TWA (Dust)20 Million parti- cles per cubic foot (Silica)OSHA Z-3fumes, silica69012-64-2TWA (Dust)20 Million parti- cles per cubic foot (Silica)OSHA Z-3fumes, silica69012-64-2TWA (Dust)20 Million parti- cles per cubic foot (Silica)OSHA Z-3fumes, silica69012-64-2TWA (Dust)80 mg/m3 / %SiO2OSHA Z-3fumes, silicaTWA (Dust)20 Million parti- cles per cubic foot (Silica)OSHA Z-3fumes, silicaTWA (Dust)80 mg/m3 / %SiO2OSHA Z-3			TWA (Res- pirable par- ticulate mat-		ACGIH
dust)TWA (respir- able fraction)5 mg/m3OSHA Z-1TWA (Total dust)10 mg/m3OSHA POTWA (Total dust)10 mg/m3OSHA POTWA (respir- able dust fraction)5 mg/m3OSHA POTWA (respir- able dust 	Portland Cement	65997-15-1	pirable par- ticulate mat-	1 mg/m3	ACGIH
able fraction)TWA (Total dust)10 mg/m3OSHA P0TWA (respir- able dust fraction)5 mg/m3OSHA P0TWA (respir- 			dust)		
dust)TWA (respirable dust fraction)5 mg/m3OSHA P0TWA (Dust)50 Million particles per cubic footOSHA Z-3TWA (Total)10 mg/m3OSHA P0TWA (Total)10 mg/m3OSHA P0TWA (Total)10 mg/m3OSHA P0TWA (Respirable fraction)5 mg/m3OSHA P0fumes, silica69012-64-2TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3fumes, silica69012-64-2TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3fumes, silica69012-64-2TWA (Dust)80 mg/m3 / %SiO2OSHA Z-3fumes, silicaTWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3fumes, silicaTWA (Dust)80 mg/m3 / %SiO2OSHA Z-3fumes, silicaTWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3fumes, silicaTWA (Dust)80 mg/m3 / %SiO2OSHA Z-3fumes, silicaTWA (Dust)80 mg/m3 / %SiO2OSHA Z-3			able fraction)		
able dust fraction)able dust fraction)OSHA Z-3TWA (Dust)50 Million parti- cles per cubic footOSHA P0TWA (Total)10 mg/m3OSHA P0TWA (Res- pirable frac- tion)5 mg/m3OSHA P0fumes, silica69012-64-2TWA (Dust)20 Million parti- cles per cubic foot (Silica)OSHA Z-3fumes, silica69012-64-2TWA (Dust)20 Million parti- cles per cubic foot (Silica)OSHA Z-3fumes, silica69012-64-2TWA (Dust)80 mg/m3 / %SiO2 (Silica)OSHA Z-3fumes, silicaTWA (Dust)80 mg/m3 / (Silica)OSHA Z-3fumes, silicaTWA (Dust)20 Million parti- cles per cubic foot (Silica)OSHA Z-3fumes, silicaTWA (Dust)80 mg/m3 / (Silica)OSHA Z-3fumes, silicaTWA (Dust)80 mg/m3 / (Silica)OSHA Z-3fumes, silicaTWA (Dust)80 mg/m3 / %SiO2OSHA Z-3			dust)		
TWA (Dust)50 Million particles per cubic footOSHA Z-3 cles per cubic footTWA (Total)10 mg/m3OSHA P0TWA (Res- pirable frac- tion)5 mg/m3OSHA P0fumes, silica69012-64-2TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3 cles per cubic foot (Silica)fumes, silica69012-64-2TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3 ocles per cubic foot (Silica)fumes, silica69012-64-2TWA (Dust)80 mg/m3 / %SiO2 (Silica)OSHA Z-3 %SiO2 (Silica)fumes, silicaTWA (Dust)80 mg/m3 / %SiO2OSHA Z-3 %SiO2OSHA Z-3 %SiO2			able dust	5 mg/m3	OSHA P0
TWA (Respirable fraction)5 mg/m3OSHA P0fumes, silica69012-64-2TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3fumes, silica69012-64-2TWA (Dust)80 mg/m3 / %SiO2 (Silica)OSHA Z-3TWA (Dust)TWA (Dust)80 mg/m3 / (Silica)OSHA Z-3TWA (Dust)TWA (Dust)80 mg/m3 / (Silica)OSHA Z-3TWA (Dust)TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3TWA (Dust)TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3TWA (Dust)TWA (Dust)80 mg/m3 / %SiO2OSHA Z-3					OSHA Z-3
pirable fraction)pirable fraction)fumes, silica69012-64-2TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3TWA (Dust)80 mg/m3 / %SiO2 (Silica)OSHA Z-3OSHA Z-3TWA (Dust)80 mg/m3 / %SiO2 (Silica)OSHA Z-3OSHA Z-3TWA (Dust)TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3TWA (Dust)TWA (Dust)20 Million particles per cubic foot (Silica)OSHA Z-3TWA (Dust)TWA (Dust)80 mg/m3 / %SiO2OSHA Z-3			TWA (Total)	10 mg/m3	OSHA P0
Image: Constraint of the system Cles per cubic foot (Silica) TWA (Dust) 80 mg/m3 / SiO2 (Silica) TWA (Dust) 20 Million particles per cubic foot (Silica) TWA (Dust) 20 Million particles per cubic foot (Silica) TWA (Dust) 80 mg/m3 / OSHA Z-3 TWA (Dust) 80 mg/m3 / OSHA Z-3 TWA (Dust) 80 mg/m3 / SiO2			pirable frac-	5 mg/m3	OSHA P0
TWA (Dust) 80 mg/m3 / %SiO2 (Silica) OSHA Z-3 TWA (Dust) 20 Million parti- cles per cubic foot (Silica) OSHA Z-3 TWA (Dust) 80 mg/m3 / %SiO2 OSHA Z-3	fumes, silica	69012-64-2	TWA (Dust)	cles per cubic foot	OSHA Z-3
TWA (Dust) 20 Million parti- cles per cubic foot (Silica) OSHA Z-3 TWA (Dust) 80 mg/m3 / %SiO2 OSHA Z-3			TWA (Dust)	80 mg/m3 / %SiO2	OSHA Z-3
TWA (Dust) 80 mg/m3 / OSHA Z-3 %SiO2			TWA (Dust)	20 Million parti- cles per cubic foot	OSHA Z-3
			TWA (Dust)	80 mg/m3 /	OSHA Z-3

Print Date 06/05/2024

The above constituents are the only constituents of the product which have a PEL, TLV or other recommended exposure limit. At this time, the other constituents have no known exposure limits.

Particles of nuisance dust

Form of exposure	Value type	Control parameters			
total dust	TWA	15 mg/m3	OSHA Z-3		
respirable fraction	TWA	5 mg/m3	OSHA Z-3		
Engineering measures :	Use of adequate ventilation should be sufficient to control worker exposure to airborne contaminants. If the use of this product generates dust, fumes, gas, vapor or mist, use pro- cess enclosures, local exhaust ventilation or other engineer- ing controls to keep worker exposure below any recommend- ed or statutory limits.				
Personal protective equipment					
Respiratory protection :	Use a properly fitted NIOSH approved air-purifying or air-fed respirator complying with an approved standard if a risk as- sessment indicates this is necessary.				
	The filter class for the respirator must be suitable for the max- imum expected contaminant concentration (gas/vapor/aerosol/particulates) that may arise when han- dling the product. If this concentration is exceeded, self- contained breathing apparatus must be used.				
Hand protection :	Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.				
Eye protection :		lying with an approved s assessment indicates thi			
Skin and body protection :	Choose body protection in relation to its type, to the concen- tration and amount of dangerous substances, and to the spe- cific work-place.				
Hygiene measures :	the product.	reaks and immediately a d clothing and protective g areas.	Ũ		

SECTION 9. PHYSICAL AND CHEMICAL PROPERTIES

Revision Date 06/05/2024

Jika

sion Date 06/05/2024		
Appearance	:	powder
Color	:	gray
Odor	:	odorless
Odor Threshold	:	No data available
рН	:	Not applicable
Melting point/range / Freezing	:	No data available
point Boiling point/boiling range	:	No data available
Flash point	:	Not applicable
Evaporation rate	:	No data available
Flammability (solid, gas)	:	No data available
Upper explosion limit / Upper flammability limit	:	No data available
Lower explosion limit / Lower flammability limit	:	No data available
Vapor pressure	:	No data available
Relative vapor density	:	No data available
Density	:	ca. 2.76 g/cm3 (68 °F / 20 °C)
Solubility(ies) Water solubility	:	insoluble
Solubility in other solvents	:	No data available
Partition coefficient: n- octanol/water	:	No data available
Autoignition temperature	:	No data available
Decomposition temperature	:	No data available
Viscosity Viscosity, dynamic	:	No data available
Viscosity, kinematic	:	No data available
Explosive properties	:	No data available
Oxidizing properties	:	No data available

Print Date 06/05/2024



Revision Date 06/05/2024

Volatile organic compounds	:	1 g/l
(VOC) content		Sika EpoCem Modul CA (A + B) + Part C Combined.

SECTION 10. STABILITY AND REACTIVITY

Reactivity	:	No dangerous reaction known under conditions of normal use.
Chemical stability	:	The product is chemically stable.
Possibility of hazardous reac- tions	:	Stable under recommended storage conditions.
Conditions to avoid	:	No data available
Incompatible materials	:	No data available
Hazardous decomposition products	:	No decomposition if stored and applied as directed.

SECTION 11. TOXICOLOGICAL INFORMATION

Not classified due to lack of data.

Skin corrosion/irritation

Causes severe burns.

Serious eye damage/eye irritation

Causes serious eye damage.

Respiratory or skin sensitization

Skin sensitization

May cause an allergic skin reaction.

Respiratory sensitization

Not classified due to lack of data.

Germ cell mutagenicity

Not classified due to lack of data.

Carcinogenicity

May cause ca IARC	ncer by inhalation. Group 1: Carcinogenic to humans Quartz (SiO2) (Silica dust, crystalline)	14808-60-7
OSHA	OSHA specifically regulated carcinogen Quartz (SiO2) (crystalline silica)	14808-60-7
NTP	Known to be human carcinogen	



Revision Date 06/05/2024

Print Date 06/05/2024

Quartz (SiO2) (Silica, Crystalline (Respirable Size)) 14808-60-7

Reproductive toxicity

Not classified due to lack of data.

STOT-single exposure

May cause respiratory irritation.

STOT-repeated exposure

Causes damage to organs (Lungs) through prolonged or repeated exposure. Once sensitized, a severe allergic reaction may occur when subsequently exposed to very low levels. Prolonged exposure can cause silicosis.

Aspiration toxicity

Not classified due to lack of data.

Further information

Product:

Quartz (14808-60-7): This classification is relevant when exposed to Quartz (silicon dioxide) in dust or powder form only, including cured product that is subject to sanding, grinding, cutting, or other surface preparation activities.

SECTION 12. ECOLOGICAL INFORMATION

Ecotoxicity No data available	
Persistence and degradability No data available	
Bioaccumulative potential No data available	
Mobility in soil No data available	
Other adverse effects	
Product:	
Additional ecological infor- : mation	Do not empty into drains; dispose of this material and its con- tainer in a safe way.

Disposal methods

Waste from residues : Dis

Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental



Revision Date 06/05/2024		Print Date 06/05/202	24
		protection and waste disposal legislation and any regional local authority requirements.	
Contaminated packaging	:	Empty containers should be taken to an approved waste han- dling site for recycling or disposal.	

SECTION 14. TRANSPORT INFORMATION

International Regulations

IATA-DGR Not regulated as a dangerous good

IMDG-Code Not regulated as a dangerous good

Domestic regulation

49 CFR Not regulated as a dangerous good

SECTION 15. REGULATORY INFORMATION

TSCA list

: All chemical substances in this product are either listed as active on the TSCA Inventory or are in compliance with a TSCA Inventory exemption.

No substances are subject to a Significant New Use Rule.

No substances are subject to TSCA 12(b) export notification requirements.

CERCLA Reportable Quantity

This material does not contain any components with a CERCLA RQ.

SARA 304 Extremely Hazardous Substances Reportable Quantity

This material does not contain any components with a section 304 EHS RQ.

SARA 302 Extremely Hazardous Substances Threshold Planning Quantity

This material does not contain any components with a section 302 EHS TPQ.

SARA 311/312 Hazards	 Respiratory or skin sensitization Carcinogenicity Specific target organ toxicity (single or repeated exposure) Skin corrosion or irritation Serious eye damage or eye irritation
SARA 313	This material does not contain any chemical components with known CAS numbers that exceed the threshold (De Minimis) reporting levels established by SARA Title III, Section 313.

Revision Date 06/05/2024

Print Date 06/05/2024

Clean Air Act

This product does not contain any hazardous air pollutants (HAP), as defined by the U.S. Clean Air Act Section 112 (40 CFR 61).

California Prop. 65

▲ WARNING: This product can expose you to chemicals including Quartz (SiO2) >5µm, which is known to the State of California to cause cancer, and Portland Cement, which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.

SECTION 16. OTHER INFORMATION

Full text of other abbreviations

ACGIH OSHA CARC	:	USA. ACGIH Threshold Limit Values (TLV) OSHA Specifically Regulated Chemicals/Carcinogens
OSHA P0	:	USA. Table Z-1-A Limits for Air Contaminants (1989 vacated values)
OSHA Z-1	:	USA. Occupational Exposure Limits (OSHA) - Table Z-1 Lim- its for Air Contaminants
OSHA Z-3	:	USA. Occupational Exposure Limits (OSHA) - Table Z-3 Min- eral Dusts
ACGIH / TWA	:	8-hour, time-weighted average
OSHA CARC / PEL	:	Permissible exposure limit (PEL)
OSHA P0 / TWA	:	8-hour time weighted average
OSHA Z-1 / TWA	:	8-hour time weighted average
OSHA Z-3 / TWA	:	8-hour time weighted average

Notes to Reader

The information contained in this Safety Data Sheet applies only to the actual Sika Corporation ("Sika") product identified and described herein. This information is not intended to address, nor does it address the use or application of the identified Sika product in combination with any other material, product or process. All of the information set forth herein is based on technical data regarding the identified product that Sika believes to be reliable as of the date hereof. Prior to each use of any Sika product, the user must always read and follow the warnings and instructions on the product's current Product Data Sheet, product label and Safety Data Sheet for each Sika product, which are available at web site and/or telephone number listed in Section 1 of this SDS.

SIKA MAKES NO WARRANTIES EXPRESS OR IMPLIED AND ASSUMES NO LIABILITY ARISING FROM THIS INFORMATION OR ITS USE. SIKA SHALL NOT BE LIABLE UNDER ANY LEGAL THEORY FOR SPECIAL OR CONSEQUENTIAL DAMAGES AND SHALL NOT BE RESPONSIBLE FOR THE USE OF THIS PRODUCT IN A MANNER TO INFRINGE ON ANY PATENT OR ANY OTHER INTELLECTUAL PROPERTY RIGHTS HELD BY OTHERS.

All sales of Sika products are subject to its current terms and conditions of sale available at www.sikausa.com or 201-933-8800.

Revision Date 06/05/2024



Revision Date 06/05/2024

Print Date 06/05/2024

000000604487 US / Z8